STATE OF TEXAS WELL REPORT for Tracking #527399					
Owner:	Camp Howdy Ranch LLC	Owner Well #:	1		
Address:	3701 E. Saunders Laredo , TX  78041	Grid #:	85-45-9		
Well Location:	Highway 83 South Laredo, TX 78040	Latitude:	27° 15' 27" N		
		Longitude:	099° 23' 26" W		
Well County:	Zapata	Elevation:	380 ft. above sea level		
Type of Work:	New Well	Proposed Use:	Stock		

Drilling Start Date: 10/28/2019 Drilling End Date: 11/15/2019

	Diameter (in.,	) Top Dept	h (ft.)	Bottom Depth (ft.)	
Borehole:	7	8		500	
Drilling Method:	Mud (Hydraulic)	Rotary			
Borehole Completion:	Screened				
	Top Depth (ft.)	Bottom Depth (ft.)	De	scription (number of sacks & material)	
Annular Seal Data:	0	20		Cement 15 Bags/Sacks	
Seal Method: <b>Poured</b> Distance to Property Line (ft.): <b>50 plus</b>					
Sealed By: Dr			c Field or other ntamination (ft.): <b>100 plus</b>		
	Distance to Septic Tank (ft.): 100 plus				
			Metho	d of Verification: measuring tape	
Surface Completion:	Irface Completion: Surface Slab Installed		Surface Completion by Driller		
Water Level: 47 ft. below land surface on 2019-11-15 Measurement Method: Sonic/Rada			urement Method: Sonic/Radar		
Packers:	No Data				
Type of Pump:	Submersible Pump Depth (ft.): 340				
Well Tests:	Pump Yield: 30 GPM with 120 ft. drawdown after 48 hours				

	Strata Depth (ft.)	Water Type		
Water Quality:	180 - 220	No Data	_	
	340 - 430	No Data	_	
	460 - 500	No Data	_	
		Chemical Analysis Made	: Yes	
	Did the driller	knowingly penetrate any strata which contained injurious constituents?		
Certification Data:	driller's direct superv correct. The driller u	nat the driller drilled this well (or the w rision) and that each and all of the sta Inderstood that failure to complete the eturned for completion and resubmitta	tements he required it	rein are true and
	driller's direct superv correct. The driller u the report(s) being re	rision) and that each and all of the sta inderstood that failure to complete the eturned for completion and resubmitta	tements he required it	rein are true and
Certification Data: Company Information:	driller's direct superv correct. The driller u the report(s) being re	vision) and that each and all of the sta understood that failure to complete the eturned for completion and resubmitta <b>Tell Drilling</b>	tements he required it	rein are true and
	driller's direct superv correct. The driller u the report(s) being re Palacios Water W 3011 San Eduardo	vision) and that each and all of the sta understood that failure to complete the eturned for completion and resubmitta <b>Tell Drilling</b>	tements he required it	rein are true and

## Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

## Casing: BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description
0	20	top brown soil
40	60	clay
80	100	clay and sand grey
120	140	light brown clay
160	180	grey shale light
200	220	grey shale
240	260	clay sand light grey
280	340	light grey shale
360	400	sand and clay
420	500	light grey shale

Dla (in.)	Туре	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
5		New Plastic (PVC)	40 1.52	0	500

## IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540