STATE OF TEXAS WELL REPORT for Tracking #315428			
Owner:	Juan Hernandez	Owner Well #:	1
Address:	806 Plymouth Ln Laredo, TX 78041	Grid #:	85-06-1
Well Location:	South east of Encinal,Tx	Latitude:	27° 57' 48" N
	Encinal,Tx., TX 78045	Longitude:	099° 21' 28" W
Well County:	Webb	Elevation:	522 ft. above sea level
Type of Work:	New Well	Proposed Use:	Domestic

Drilling Start Date: 3/25/2013 Drilling End Date: 3/27/2013

	Diameter (in.) Top De	epth (ft.)	Bottom Depth (ft.)	
Borehole:	10		D	30	
	7	3	0	500	
Drilling Method:	Air Rotary				
Borehole Completion:	Straight Wall				
	Top Depth (ft.)	Bottom Depth (ft.)	Des	scription (number of sacks & material)	
Annular Seal Data:	0	11		12 cement mix	
	11	100		15 holeplug	
	100	420		18portland1gel	
Seal Method: cir	rculation,plug and	basket Di	stance to Pro	operty Line (ft.): 1320	
Sealed By: Driller		Distance to Septic Field or other concentrated contamination (ft.): none present			
		I	Distance to S	Septic Tank (ft.): No Data	
			Method	d of Verification: odometer	
Surface Completion:	Surface Sleeve Ir	nstalled			
Water Level:	102 ft. below land surface, and 0 GPM Measurement Method: Unknown artesian flow on 2013-04-08				
Packers:	0				
Type of Pump:	Submersible Pump Depth (ft.): 260				
Well Tests:	Jetted	Yield: 60 GPM v	with 320 ft. (drawdown after 2 hours	

	Strata Depth (ft.)	Water Type		
Water Quality:	422 - 490	good		
		Chemical Analysis Ma	ade: No	
	Did the driller	knowingly penetrate any strata wh contained injurious constituen		
Certification Data:	driller's direct superv correct. The driller u	nat the driller drilled this well (or the ision) and that each and all of the inderstood that failure to complete eturned for completion and resubm	statements he the required it	rein are true and
Certification Data: Company Information:	driller's direct superv correct. The driller u the report(s) being re	ision) and that each and all of the inderstood that failure to complete eturned for completion and resubm	statements he the required it	rein are true and
	driller's direct superv correct. The driller u the report(s) being re	ision) and that each and all of the inderstood that failure to complete eturned for completion and resubm o.	statements he the required it	rein are true and
	driller's direct superv correct. The driller u the report(s) being re Woods Drilling Co P.O. Box 440190	ision) and that each and all of the inderstood that failure to complete eturned for completion and resubm b .	statements he the required it	rein are true and

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	8	topsoil
8	14	caliche
14	29	siltstone & clay yellowtan
29	422	sandy gray shale
422	490	sand gray to graywhite
490	500	sandy shale gray

Casing:
BLANK PIPE & WELL SCREEN DATA

Dia. (in.) New/Used Type Setting From/To (ft.) 4 1/2"I.D. New SDR-17 pvc plain +2 - 420'

4 1/2"I.D. New SDR-17 pvc perf 420 - 500 3/8"

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540